



TRANSPARENT WATER BASED COATING

Application

Brush or roll (e.g. with mini gloss style roller) directly onto the porous substrate.

Curing

Air dry for 24 hours.

Please note; a more effective sublimation transfer result can be achieved by a 2nd application and cure, prior to printing / pressing.